Work Order ID 64915

December 22, 2010 3:11:11 PM

, a	 	

Page 1

Item ID:

DSI 9226-011

Accept

Setup Start

Stop



Revision ID:

Item Name:

Basket Conversion

Start Date:

Required Date: 12/23/10

12/22/10

Start Qty: 1.00

Req'd Qty: 1.00



Cust Item ID:

Customer:

Reference:

Approvals:

Process Plan:

Operation

Description

Date:

Tooling:

Date:

Run

Reject

Qty

Start

Stop



QC:

Date:

SPC (Y/N):

Set Up/

Run Hours

Tool ID

Tool # Plan Code

Accept Qty

Reject Number

Insp. Stamp

Work Center ID **Draw Nbr**

Sequence ID/

Revision Nbr

Rev A

DSI 9226

100

DC

Document Control

DOCUMENT CONTROL

Memo

Memo

0.00

0.00

Photocopy bluefile D205-541 and create labels per PPP DSI 9226 CHG001

110



QC4-100% Inspect kits for completeness

Pich hit

0.00

0.00

Swheles

Quality Control

120

Packaging Packaging

Packaging

Memo

0.00

0.00

Identify and pack for shipping as per PPP DSI 9226-011

Page 2

December 22, 2010 3:11:11 PM

Item ID:

DSI 9226-011

Accept



Setup Start

Stop



Revision ID:

Item Name:

Basket Conversion

Start Date:

Required Date: 12/23/10

12/22/10

Start Qty: 1.00

Req'd Qty: 1.00

QC21- Final Inspection - Work Order Release



Cust Item ID: Customer:

Reference:

Approvals:

QC:

Process Plan:

Operation

Description

Date:

Date: **Tooling:**

SPC (Y/N):

Set Up/

Run Hours

Date:

Date:

Start Run

Stop



Sequence ID/

Work Center ID

130

Memo

0.00

0.00

Tool ID

Tool # Plan

Qty Code

Reject Accept Qty

Reject Number

Insp. Stamp

Quality Control

•	•	
	Picklist Pri	
¥	December 22, 20	10
	Work Order ID:	649
	Parent Item:	DS
	Parent Item Name	٠.

010 3:11:08 PM

64915

DSI 9226-011

Basket Conversion



Start Date: 12/22/10

Start Qty: 1.00

Required Date: 12/23/10

Page 1

Required Qty: 1.00

Comments:	PP A□02.02.05	INew Issue[IN	GΠ										
Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date St Issued	atus
AN4-12A		Purchased	No			110	Each	278.0000	1	1			
					112314 · 115371	<u>Loc (</u>	Oty 278 78 40 160	Loc Code		n//23	314	,	1
AN4-13A		Purchased	No			110	Each	274.0000	3	3 ~	· · · · · · · · · · · · · · · · · · ·	(d)	, ,
				Location ST357	116191	<u>Loc</u>	<u>Oty</u> 274 274	Loc Code	, <u>,</u>	M116[9/	4	
AN4-14A 		Purchased	No			110	Each	142.0000		1 6		/4/12/2	_3(
				Location ST357	ļ.	Loc	Oty 1	Loc Code					

Location	Loc Qty	Loc Code	
ST357	1		
114752	1		
ST358	5		***
110372	2		
113359	3		
t357	136		
116419	136		M1/641
			/

Shop Packet Print

Page 2

December 22, 2010 3:11:09 PM

December 22, 2010 3:11:09 PM

Work Order ID: 64915

Parent Item:

DSI 9226-011

Parent Item Name:

Basket Conversion



Start Date: 12/22/10

Required Date: 12/23/10

Start Qty: 1.00

Required Qty: 1.00

D2515

Bushing

Manufactured No 110

Each

41.0000

Loc Code

D3052-1

Mounting Lug

Manufactured No

ST017

Location

110

110

40 Each

41

Loc Qty

28.0000

Loc Code

∠MS21042L4

Purchased No Location ST472

40200

29138 40927

> Loc Qty 28 28

> > Each

4,242.000

Location Loc Qty ST300 4242 1123143 2 115589 10 115621 730 116188 3500

Loc Code



DESIG	* #	DRAWN BY	DART AEROSPACE HAWKESBURY, ONTARIO, CAN	
CHECK	KED A	APPROVED	DRAWING NO.	REV. A
	#	1 <i>Q</i>	DSI 9226	SHEET 1 OF 1
DATE	7.4	1-73	TITLE	SCALE
02.0	01.16		BASKET CONVERSION KIT	NTS
Α		02.01.16	NEW ISSUE	


DART SERVICE INSTRUCTION

TO AMEND INSTALLATION INSTRUCTIONS: D205-541 REV. E

REFERENCE ONLY

REF. CANADIAN STC: SH96-120 FAA STC: SR00696NY

THE PURPOSE OF THIS SERVICE INSTRUCTION IS TO OUTLINE THE PROCEDURE FOR CONVERTING A D205-541-041 BASKET INTO A D205-541-044 BASKET USING THE DSI 9226-011 KIT.



NOTES:

- CUT 0.75" +0.06/-0.00 GAP IN THE RIBS SHOWN (3 PLACES) AT A DISTANCE OF 44.710" FROM FWD END OF THE BASKET AS SHOWN.
- WELD IN D2235-3 RIB AS SHOWN. TIG WELD PER MIL-STD-2219/AMS-STD-2219 CLASS "C" USING ER308L FILLER ROD.
- TOUCH UP PAINT AS REQUIRED USING 1 COAT OF MIL-P-85582 OR MIL-P-23377 PRIMER AND 2-3 COATS OF MIL-C-85285 POLYURETHANE PAINT.
- INSTALL D3052-1 MOUNTING LUG PER D205-541 REV. E.
- REPLACE D2258-220 LABEL WITH D2258-300 LABEL.
- INSTALL BASKET ON A/C PER D205-541 REV. E. 6)
- REPLACE D205-541 REV. D, MMS-D205-541 REV. D, AND FMS-D205-541 REV. C WITH D205-541 REV. E, ICA-D205-541 REV. 0, AND FMS-205-541 REV. D.

Qty -011	Part Number	Description
Х	DSI 9226-011	BASKET CONVERSION KIT
1	D2199-1	STRUT
: 1	D2235-3	RIB
1	D2258-300	L'ABEL
. 1	D2515	BUSHING
i 1	D3052-1	MOUNTING LUG
7 1	AN4-12A	BOLT
3	AN4-13A	BOLT
1	AN4-14A	BOLT
1	AN4-7A	BOLT
10	AN960JD416	WASHER
6	MS21042L4	NUT (or MS21042-4)

CANADA DEPARTMENT OF TRANSPORT AIRCRAFT CERTIFICATION **BRANCH** DAO # 01-O-01 PPROVED D. SHEPHERD (DE # 02) DATE: Jan. 16 2002 CERT. NO .: SH96-120 ISSUE NO .: #2